

Date: Fri, 15 May 1998 08:03:41 -0500
From: Meredith Brown <racer@lanl.gov>
Subject: Update to LL 1998-RL-HNF-0004

Lessons Learned YELLOW/Caution 1998-RL-HNF-0004 described three recent drum handling incidents and discussed safe drum handling techniques. Crosby Group, Inc. has since developed a new drum lifting rig that uses three drum clips and a center ring to hold them firmly on the drum. Update 1 to the subject Lessons Learned contains graphics showing the construction and operation of the new designs. This lifting ring could significantly reduce the potential for dropped waste drums if used correctly.

Because of the difficulty transmitting graphics through the numerous gateways in our communication systems and the wide variety of e-mail systems across DOE, you are encouraged to access the Lessons Learned directly at

URL: <http://www.hanford.gov/lessons/sitell/l198/199804-1.htm>

Please call me at (509) 373-7664 if you have trouble accessing that location.

John Bickford Project Hanford Lessons Learned Coordinator (509)373-7664 FAX:(509)376-5243 e-mail: John_C_Bickford@rl.gov